

UNDERWATER BRIDGE INSPECTION REPORT

STRUCTURE NO. 96026

MSAS 119

OVER

POND OUTLET

DISTRICT 1 – ST. LOUIS COUNTY, CITY OF DULUTH



PREPARED FOR THE

MINNESOTA DEPARTMENT OF TRANSPORTATION

BY

COLLINS ENGINEERS, INC.

JOB NO. 5221

MINNESOTA DEPARTMENT OF TRANSPORTATION
UNDERWATER BRIDGE INSPECTION

REPORT SUMMARY:

The substructure inspected at structure No. 96026, a concrete box culvert, was found to be in good condition with no defects of structural significance.

INSPECTION FINDINGS:


- (A) Joints between culvert sections exhibited from ¼ to 1 inch maximum horizontal openings (acceptable for tongue and groove arrangement), and vertically, there was up to a ½ inch differential across various joints.
- (B) The channel bottom consisted of sandy infilling at west opening. From entrance to 15 feet into the structure, the channel bottom consisted of riprap on the culvert floor, and after that, the channel bottom consisted of sand and gravel on the culvert floor.

RECOMMENDATIONS:

- (A) Reinspect the submerged substructure units at the normal maximum recommended (NBIS) interval of five (5) years.

I hereby certify that this plan, specification, or report was prepared by me or under my direct supervision and that I am a duly Licensed Professional Engineer under the laws of the State of Minnesota.


Daniel G. Stromberg



Date 6/30/2008 Registration No. 21491

Respectfully submitted,

COLLINS ENGINEERS, INC.



Daniel G. Stromberg
Registered Professional
Engineer, State of Minnesota

MINNESOTA DEPARTMENT OF TRANSPORTATION
UNDERWATER BRIDGE INSPECTION

1. BRIDGE DATA

Bridge Number: 96026

Feature Crossed: Pond Outlet

Feature Carried: MSAS 119

Location: District 1 – St. Louis County, City of Duluth

Bridge Description: The structure consists of a precast concrete box culvert (10 foot wide opening).

2. INSPECTION DATA

Professional Engineer Diver: Daniel G. Stromberg, P.E., S.E.

Dive Team: Clayton G. Brookins, Valerie Roustan

Date: October 15, 2007

Weather Conditions: Partly Cloudy, 48° F

Underwater Visibility: None / Negligible

Waterway Velocity: None / Negligible

3. SUBSTRUCTURE INSPECTION DATA

Substructure Inspected: Culvert.

General Shape: Precast Box Culvert.

Maximum Water Depth at Substructure Inspected: Approximately 6.0 feet.

4. WATERLINE DATUM

Water Level Reference: Underside of culvert top slab at west opening.

Water Surface: The waterline was approximately 6.0 inches below the reference.

Assumed Waterline Elevation 99.5.

5. NBIS CODING INFORMATION (Minnesota specific codes are used for 92B and 113)

Item 60: Substructure: Code 7

Item 61: Channel and Channel Protection: Code 8

Item 92B: Underwater Inspection: Code B/10/07

Item 113: Scour Critical Bridges: Code E/07

Bridge is scour critical because abutment or pier foundation is rated as unstable due to observed scour at bridge site.

 Yes X No



Photograph 1. View of West Opening, Looking Southwest.



Photograph 2. View of East Opening, Looking West.

MINNESOTA DEPARTMENT OF TRANSPORTATION
OFFICE OF BRIDGES AND STRUCTURES
DAILY DIVING REPORT

INSPECTORS: Collins Engineers, Inc. DATE: October 15, 2007

ON-SITE TEAM LEADER: Daniel G. Stromberg, P.E., S.E.

BRIDGE NO: 96026 WEATHER: Partly Cloudy, 48° F

WATERWAY CROSSED: Storm Sewer

DIVING OPERATION: _____ SCUBA ☒ SURFACE SUPPLIED AIR
_____ OTHER _____

PERSONNEL: Clayton G. Brookins, Valerie Roustan

EQUIPMENT: Scuba, U/W Light, Scraper, Lead Line, Probe Rod, Camera

TIME IN WATER: 4:30 p.m.

TIME OUT OF WATER: 5:00 p.m.

WATERWAY DATA: VELOCITY None / Negligible

VISIBILITY None / Negligible


DEPTH 6.0 feet maximum

ELEMENTS INSPECTED: Culvert

REMARKS: Overall, the concrete of the structure was smooth and sound with no notable deterioration. Joints between culvert sections exhibited from 1/4 to 1 inch maximum horizontal openings (acceptable for tongue and groove arrangement), and vertically, there was up to a 1/2 inch differential across various joints. The channel bottom consisted of sandy infilling at west opening. From entrance to 15 feet into the structure, the channel bottom consisted of riprap on the culvert floor, and after that, the channel bottom consisted of sand and gravel on the culvert floor.



FURTHER ACTION NEEDED: _____ YES ☒ NO

Reinspect the submerged substructure units at the normal maximum recommended (NBIS) interval of five (5) years.



INSPECTION NOTES:

- 1 The concrete was in smooth and sound condition. The joints between culvert segments exhibited 1/4- to 1-inch-wide horizontal gaps (acceptable for tongue and groove joint arrangement) and up to 1/2-inch differentials across adjacent faces at various joints.
- 2 The channel bottom consisted of sandy infilling (up to 3 feet deep) on culvert floor.
- 3 The channel bottom consisted of riprap with no probe rod penetration for a length of 15 feet along the northwestern end of the box culvert.



SOUTHEASTERN END VIEW OF CULVERT

GENERAL NOTES:

1. The entire length of the box culvert was inspected underwater.
2. At the time of inspection, on October 15, 2007, the waterline was located approximately 6 inches below the top of the box culvert opening at the westerly headwall. Since insufficient elevation information was available, a waterline reference of 100.0 was assumed. This corresponds to a waterline elevation of 99.5.
3. Soundings indicate the water depth at the time of inspection and are measured in feet.
4. Soundings were taken at approximately 10 foot intervals along the length of the box culvert.

Legend

-0.4 Sounding Depth (10/15/07)

MINNESOTA DEPARTMENT OF TRANSPORTATION UNDERWATER BRIDGE INSPECTION


STRUCTURE NO. 96026
OVER STREAM
DISTRICT 1, ST. LOUIS COUNTY

INSPECTION AND SOUNDING PLAN

Drawn By: MDK
Checked By: DGS
Code: 52216026

COLLINS
ENGINEERS
123 North Wacker Drive
Suite 300
Chicago, IL 60606
(312) 704-9300
www.collinsengr.com

Date: OCT. 2007
Scale: NTS
Figure No.: 1



☺ CULVERT PROFILE

Note:

Refer to Figure 1 for General Notes.

**MINNESOTA
DEPARTMENT OF TRANSPORTATION
UNDERWATER BRIDGE INSPECTION**

STRUCTURE NO. 96026
OVER STREAM
DISTRICT 1, ST. LOUIS COUNTY
**CENTERLINE ELEVATION
PROFILE**

Drawn By: MDK

Checked By: DGS

Code: 52216026

**COLLINS
ENGINEERS**

123 North Wacker Drive
Suite 300
Chicago, IL 60606
(312) 704-9300
www.collinsengr.com

Date: OCT. 2007

Scale: NTS

Figure No.: 2

MINNESOTA DEPARTMENT OF TRANSPORTATION
OFFICE OF BRIDGES AND STRUCTURES
DAILY DIVING REPORT

INSPECTORS: Collins Engineers, Inc. DATE: October 15, 2007

ON-SITE TEAM LEADER: Daniel G. Stromberg, P.E., S.E.

BRIDGE NO: 96026 WEATHER: Partly Cloudy, 48° F

WATERWAY CROSSED: Storm Sewer

DIVING OPERATION: _____ SCUBA X SURFACE SUPPLIED AIR
_____ OTHER _____

PERSONNEL: Clayton G. Brookins, Valerie Roustan

EQUIPMENT: Scuba, U/W Light, Scraper, Lead Line, Probe Rod, Camera

TIME IN WATER: 4:30 p.m.

TIME OUT OF WATER: 5:00 p.m.

WATERWAY DATA: VELOCITY None / Negligible

VISIBILITY None / Negligible

DEPTH 6.0 feet maximum

ELEMENTS INSPECTED: Culvert

REMARKS: Overall, the concrete of the structure was smooth and sound with no notable deterioration. Joints between culvert sections exhibited from 1/4 to 1 inch maximum horizontal openings (acceptable for tongue and groove arrangement), and vertically, there was up to a 1/2 inch differential across various joints. The channel bottom consisted of sandy infilling at west opening. From entrance to 15 feet into the structure, the channel bottom consisted of riprap on the culvert floor, and after that, the channel bottom consisted of sand and gravel on the culvert floor.

FURTHER ACTION NEEDED: _____ YES X NO

Reinspect the submerged substructure units at the normal maximum recommended (NBIS) interval of five (5) years.

MINNESOTA DEPARTMENT OF TRANSPORTATION
OFFICE OF BRIDGES AND STRUCTURES

UNDERWATER INSPECTION CONDITION RATING FORM

BRIDGE NO. 96026
INSPECTORS Collins Engineers, Inc.
ON-SITE TEAM LEADER Daniel G. Stromberg, P.E., S.E.
WATERWAY CROSSED Pond Outlet

INSPECTION DATE October 15, 2007
NOTE: USE ALL APPLICABLE CONDITION
DEFINITIONS AS DEFINED IN THE MINNESOTA
RECORDING AND CODING GUIDE INCLUDING
GENERAL, SUBSTRUCTURE, CHANNEL AND
PROTECTION, AND CULVERTS AND WALL
DEFINITIONS TO COMPLETE THIS FORM.

CONDITION RATING

UNIT REFERENCE NO.	UNIT DESCRIPTION	MAXIMUM DEPTH OF WATER	SUBSTRUCTURE						CHANNEL					GENERAL					
			PILING	COLUMNS, SHAFTS, OR FACES*	FOOTINGS	DISPLACEMENT	OTHER (BRACING)	OVERALL SUBSTRUCTURE CONDITION CODE*	SCOUR	EMBANKMENT EROSION	EMBANKMENT PROTECTION	OTHER (DRIFT/DEBRIS)	OVERALL CHANNEL & PROTECTION CONDITION	CONCRETE	STEEL	TIMBER	LOSS OF SECTION	PREVIOUS REPAIR OR MAINTENANCE	OTHER
		1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18
	Culvert	6.0'	N	7	N	8	N	7	8	N	N	N	8	7	N	N	N	N	N

*UNDERWATER PORTION ONLY

REMARKS: Overall, the concrete of the structure was smooth and sound with no notable deterioration. Joints between culvert sections exhibited from 1/4 to 1 inch maximum horizontal openings (acceptable for tongue and groove arrangement), and vertically, there was up to a 1/2 inch differential across various joints. The channel bottom consisted of sandy infilling at west opening. From entrance to 15 feet into the structure, the channel bottom consisted of riprap on the culvert floor, and after that, the channel bottom consisted of sand and gravel on the culvert floor.

NOTES: ATTACH SKETCHES AS NEEDED, IDENTIFY REMARK BY REFERRING TO UNIT REFERENCE NO. AND REMARK NO.
USE GENERAL SECTION TO IDENTIFY OVERALL PRESENCE OF SPALLS, CRACKS, CORROSION, ETC.